



## TOYABR GEL MEMORY FOAM MATTRESS TOPPER

In addition to the lifetime warranty on our gel memory foam mattress topper, Toyabr covers all of defects in the material for 10 years (from the date of purchase).

## Limitations of Warranty

The warranty does not cover cosmetic damages such as scratches, rips and tears. In addition to other outside causes such as extensive warring or other achities that may cause damage are not covered. During this precicip place contact customer service may be used to rejudy the damaged component. There will be no charge to the customer for factory months of the need to rejudy the damaged component. There will be not charge to the customer for factory

Mattress Toppers are warranted to be free from defects in materials or workman-ship for 10 year from the date of purchase. Within this period, TOYABR will, at its sole option, repair or replace any components that fall in normal use. Such repairs or replacement will be made at no charge to the customer for parts or labor.

# Legal Rights

## Warranty Service

Please contact the repair/replacement department for warranty questions or issues: Toyabr Attn: Customer Service, 630 S Hambledon Ave City of Industry CA 91744 USA Mail: market@chunyicover.com

toyabr®

# **GEL-INFUSED MEMORY FOAM MATTRESS TOPPER**






Pull the mattress topper out of the package. Cut the lastic wrapping and remove the compressed mattress topper Be careful with sharp objects for your own safety and to avoid cutting the memory foam and bamboo cover.









Please allow up to 48 hours for the mattress odor to dissipate before fully enjoying a good nights sleep on your brand new Subrtex Gel-infused Memory Foam Mattress Topper.

## Attention:

Due to the unique properties of memory foam, dimensions may subtly VARY after full expansion; it is normal and WILL NOT affect the performance of your topper.
Z Memory foam may have slight odor initially; it WILL NOT bring any harm to your body, it will dissipate over normal use.
S Discoloration to memory foam may appear over time due to oxidization of a natural process when memory foam expose under the light; it Will NOT affect the performance of your topper.









